## North America Emission Control Area Fuel Oil Non-Availability Report
## ECA0100
## 1 2 3
##
##(Include Double Pound for comments, not form fields)
##Report Form ID Ship Operator Name Vessel Name

	_		_
Δ	5	6	7
-		- U	,

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice

Marshall Islands 9274575 5-Apr-13 veracruz

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption

New Orleans Veracruz Veracruz

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA

naval mexicana 2 4/7/2013

abc Maritima

14		15 1	6
Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel O	oil Projected Hours on Main Propulsion	l
20:00	3	3.4	3

Name of First POC Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC?

New Orleans Yes Yes

19

20 21 22

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

1 N/A N/A

23 24

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC?

N/A

N/A

25

26 27

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

4/13/2012

12:00 Yes

Number of Separate Visits to the ECA Number of Ports visited in the ECA Previously submitted ECA0100 forms?

1 2 No

30

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail

N/A Vasant Nair vnair@eagleshipmgmt.com

34 35

1-646-833-2527

Designated Corporate Official Phone Number Description of Actions to Achieve Compliance Low Sulfur fuel has been stemmed at first port of call in ECA.